

OpenSSL Hotfix for 4.1 SP6

August 2002

1 Overview

This Hotfix addresses a security alert published regarding OpenSSL: CERT® Advisory CA-2002-23 “Multiple Vulnerabilities In OpenSSL”.

The issues which concern Check Point’s use of OpenSSL are also being referenced as Common Vulnerabilities and Exposures project references: CAN-2002-0656, CAN-2002-0659

The Hotfix addresses the resulting vulnerabilities, mainly originating from possible buffer overruns in the OpenSSL code.

2 Relevant versions

This Hotfix is relevant only for 4.1 SP6

3 Supported Platforms

This hot-fix is available for the following platforms:

- Solaris
- Windows
- Linux
- HPUX
- AIX
- IPSO

4 Installation

This Hotfix requires a replacement of files depending on specific deployment configurations.

4.1 *Enforcement module/ Management Server*

To apply this fix to the enforcement module – proceed as follows:

4.1.1 Windows

1. Download
 - a. WIN32: openssl_HF_41_SP6_B41623_win32_[encryption].tgz
 - b. W2K: openssl_HF_41_SP6_B41623_win2k_[encryption].tgz

to a temporary directory and extract the files to a temporary directory.

2. Using a command-line run the following commands:
‘fwstop’
3. If ELA Proxy is running - stop ELA Proxy by running the following command using the command-line:
‘net stop elservice’
4. replace fw.exe under %FWDIR%\bin

5. replace `ela_proxy.exe` under `%FWDIR%\bin`
6. Using a command-line run the following commands:
 - a. `'fwstart'`
7. To restart ELA Proxy - using the command-line run the command:
`'net start elservice'`
8. To verify that the fix is applied, open a command line window:
 - a. Change directory to `%FWDIR%`
 - b. Run `'fw ver'` and make sure that the Build Number field is the correct one:
41623

4.1.2 Unix Platforms

1. Download
 - a. Solaris: `openssl_HF_41_SP6_B41623_solaris2_[encryption].tgz`
 - b. Solaris-i386:
`openssl_HF_41_SP6_B41623_solaris2i386_[encryption].tgz`
 - c. Linux: `openssl_HF_41_SP6_B41623_linux_[encryption].tgz`
 - d. IPSO: `openssl_HF_41_SP6_B41623_ipso_[encryption].tgz`
 - e. AIX: `openssl_HF_41_SP6_B41623_aix_[encryption].tgz`
 - f. HP-UX: `openssl_HF_41_SP6_B41623_hpux_[encryption].tgz`
to a temporary directory and extract the file to a temporary directory.
2. Run the following commands
`'fwstop'`
3. If ELA Proxy is running - stop ELA Proxy by running the following command
using the command:
`'elaproxyService -stop'`
4. replace `fw` under `$FWDIR/bin`
5. replace `ela_proxy` under `$FWDIR/bin`
6. Run the following commands
`'fwstart'`
7. To restart ELA Proxy - using the command-line run the command:
`'elaproxyService -start'`
8. To verify that the fix is applied, open a command-line window:
 - a. Change directory to `$FWDIR`
 - b. Run `'fw ver'` and make sure that the Build Number field is the correct one:
41623