

MOTOROLA
Computer Group

604 SMP Support

for AIX™ 4.1.4

76707970-001

CD-ROM

© Copyright Bull S.A., 1996

TRADEMARKS

Motorola acknowledges the right of proprietors of trademarks mentioned in this book.

Motorola and the Motorola logo are registered trademarks of Motorola, Inc.

AIX is a trademark of International Business Machines Corporation, and is being used under licence.

iFOR is a trademark of Gradient Technologies.

UNIX is a registered trademark in the USA and other countries licensed exclusively through X/Open Company Limited.

The information in this document is subject to change without notice. MOTOROLA Computer Group and any other entity of MOTOROLA Inc. will not be liable for errors contained herein, or for incidental or consequential damages in connection with the use of this material.

604 SMP Support Description

This CD-ROM provides 604 SMP Support for AIX™ 4.1.4

fileset	version	PTF#
bos.rte.mp	4.1.4.12	U443184
bos.rte.up	4.1.4.12	U443194
bos.rte.libc	4.1.4.11	U443062
bos.rte.libs	4.1.4.9	U443102
bos.rte.security	4.1.4.2	U440895
bos.diag.rte	4.1.4.4	U443037
bos.adt.prof	4.1.4.11	U443061
devices.mca.8f9d.rte	4.1.4.2	U441727
devices.sio.ktma.diag	4.1.4.2	U443073
devices.isa_sio.km.diag	4.1.4.2	U443058
devices.mca.f6f8.diag	4.1.3.1	U443109
devices.mca.edd0.com	4.1.4.7	U443221

Important Upgrade Information

The AIX™ 4.1.4 software must be upgraded prior to hardware upgrade.

If this is not done, your system will not work correctly and may even not boot.

Description of the CD-ROM

This CD-ROM includes product update packages

Product update packages, i.e. installable via `smit`, are available under the directory `usr/sys/inst.images`.

The hardware upgrade instructions are described in :

Series MP and series I Server Power PC 604 Upgrade Kit - Installation Instructions 86X152GX00

Using the CD-ROM

Before You Begin

For more detailed instructions on using the CD-ROM drive, see the Read Me First documentation delivered with your system.

Handling the CD-ROM

Always handle the disc by the edge to avoid fingerprints and scratches that could affect the readability of the data stored on it.

Cleaning the CD-ROM

Dust and scratches on the CD-ROM may cause problems. Keep the CD-ROM free of dust by wiping both sides with a soft lint-free cloth or lens tissue. Always wipe in a straight line from the inner hub to the outer rim.



Upgrading AIX™ 4.1.4 software from CD-ROM

To upgrade AIX™ 4.1.4 software to support 604 SMP [1]:

1. insert the 604 SMP CD-ROM into the drive
2. logon as root user
3. install the upgrade package using smit :
   smit update_all
4. select the device for software upgrade : /dev/cd0
5. Wait until the command status is set to "OK".
6. Remove the CD-ROM.
7. Reboot the system.

---

1. must be done before hardware upgrade